

RIFLE SAFETY WARNING

SAFETY WARNING AND RECALL NOTICE

A Limited Number of Rifles are Affected

SIG SAUER, Inc. has determined that a limited number of rifles in the **SIG716 DMR**[®], **SIG516**[®] **Carbon Fiber** and **SIGM400**[®] **Predator** models are subject to a Safety Warning and Recall Notice. Some models were built with a two-stage SIG SAUER trigger that may have an improperly heat-treated hammer. Over time, this could result in a trigger malfunction creating a significant safety hazard. SIG SAUER is issuing a mandatory recall to replace the hammer and trigger assembly in these specific rifles. This recall does not affect any military or law enforcement rifles or any SIG MCX[®]/SIG MPX[®] products.

SIG SAUER will correct any of the affected firearms at no cost to the customer.

The firearms affected by the recall can be identified by the presence of a SIG mark etched into the hammer. *See image below.*



>>**CLICK HERE FOR COMPLETE NOTICE**<<