

## PRODUCT WARNING AND RECALL NOTICE

### WINCHESTER® 9mm Luger 115 grain

Olin Winchester, LLC is recalling the following lots of 9mm Luger 115 grain Full Metal Jacket and 115 grain Jacketed Hollow Point pistol ammunition.

**Symbols: Q4172, RED9, USA9JHP, USA9MMVP, USA9W, WW9B**

#### Lot Numbers:



SC03LD44, SC03LD45, SC03LD46, SC03LD47  
SC13LD1, SC13LD6, SC13LD18, SC13LD44, SC13LD45, SC13LD46, SC13LD47  
SC52LD44, SC52LD45, SC52LD46, SC52LD47  
SC62LD44, SC62LD45, SC62LD46, SC62LD47  
SC72LD44, SC72LD45, SC72LD46, SC72LD47  
SC92LD44, SC92LD45, SC92LD46, SC92LD47  
SD10LD1, SD10LD3, SD10LD6, SC10LD12, SD10LD18, SD10LD46, SD10LD47  
SD50LD1, SD50LD3, SD50LD6, SD50LD11, SD50LD12, SD50LD18, SD50LD46, SD50LD47  
SD60LD1, SD60LD3, SD60LD6, SD60LD11, SD60LD12, SD60LD18  
SD70LD1, SD70LD3, SD70LD6, SD70LD11, SD70LD12, SD70LD18  
SD80LD1, SD80LD3, SD80LD6, SD80LD11, SD80LD12, SD80LD18

The Symbol designations and locations of the Lot Numbers are depicted in the photographs below.

***NOTE: If ammunition of the above Symbols was purchased before March 25, 2021, it is NOT subject to the recall.***

Winchester has determined the above lots of 9mm Luger 115 FMJ and JHP ammunition may contain propellant that does not properly ignite and burn when the cartridge is fired. Ammunition containing propellant that does not properly ignite and burn may result in a bullet remaining in the barrel (i.e., a bullet-in-bore obstruction). Firing a subsequent bullet into the bore obstruction could cause firearm damage, rendering the firearm inoperable and subjecting the shooter and bystanders to a risk of serious personal injury.

**DO NOT USE WINCHESTER® 9MM LUGER 115 FMJ / JHP OF THE ABOVE SYMBOLS THAT HAS ANY OF THE ABOVE LOT NUMBERS.** The ammunition Lot Number is stamped on the cartons of the Symbols involved as indicated here:





**SYMBOL WW9B FIVE 100-ROUND ORIENTED BULK PACKS**



To determine if your ammunition is subject to this notice, review the Symbol and Lot Number. If it is any of the above Symbols and Lot Numbers, **immediately discontinue use** and contact Winchester toll-free at 844-653-8358 for free UPS pick-up of the recalled ammunition. Upon receipt of your recalled ammunition, Winchester will ship replacement ammunition directly to you or issue you a reimbursement check.

This notice applies only to the above 9mm Luger 115 FMJ and JHP Symbols with the above Lot Numbers. Other Symbols or Lot Numbers are not subject to this recall.

If you have any questions concerning this 9mm Luger 115 FMJ / JHP pistol ammunition recall please call toll-free 844-653-8358, write to Winchester (600 Powder Mill Road, East Alton, IL 62024 Attn: 9mm Luger Recall), or visit our website at [www.winchester.com](http://www.winchester.com).

We apologize for this inconvenience.